

Software v2.1.7 release notes

for HAMILTON-T1

Introduction

The latest software version 2.1.7 for HAMILTON-T1 is now available. It provides enhancements in ease of use and performance.

Enhancements in ease of use

Oxygen supply failed alarm

We corrected an error that could lead to false-positive "Oxygen supply failed" alarms.

ELO20160208N.00 Product and order information are subject to change without notice. Not all options are available in all countries.
© 2016 Hamilton Medical AG. All rights reserved.