

Software v2.2.1 release notes

for HAMILTON-T1

Introduction

The latest software version 2.2.1 for HAMILTON-T1 is now available, making interaction with the device easier.

Battery communication error alarm resolved

The new software incorporates enhanced battery communication management to avoid battery communication errors caused by timing issues.

Tightness test

An improved routine increases tightness test stability.

Corrected translation of software labels and error messages

To increase clarity we changed some labels in Swedish, Danish, and Dutch.

ELO20170505N.00 Product and order information are subject to change without notice. Not all options are available in all countries.
© 2017 Hamilton Medical AG. All rights reserved.